
**SUPPLEMENTAL REMEDIAL INVESTIGATION
GROUNDWATER REPORT (PART 2)
Former York Naval Ordnance Plant
1425 Eden Road
York, PA 17402**

Prepared for:

**Former York Naval Ordnance Plant Remediation Team
York, PA**

**August 2016
Revised March 2018**

**Volume 3 of 4
Figures & Plates**

Prepared by:

Groundwater Sciences Corporation

**2601 Market Place Street, Suite 310
Harrisburg, Pennsylvania 17110**

**560 Route 52, Suite 202
Beacon, New York 12508**

**1108 Vestal Parkway East, Suite 2
Vestal, New York 13850**



Figures (Volume 3 of 4)

| | |
|--------------|---|
| Figure 1.0-1 | Site Location Map |
| Figure 1.1-1 | Site Map |
| Figure 1.3-1 | Published Regional Geology |
| Figure 1.3-2 | Epikarst Surface (Top of Bedrock) Showing Total Void Footage |
| Figure 1.3-3 | 3D Color Visualization of Karst Features Plan View |
| Figure 1.3-4 | York Area Geologic Cross Section Location Key |
| Figure 1.3-5 | York Area Geologic Cross Section fYNOP Site to Roosevelt Quarry |
| Figure 1.3-6 | Overview of Fate and Transport Mechanisms (Carbonate Bedrock Setting) |
| Figure 1.3-7 | Overview of Fate and Transport Mechanisms (Non-Carbonate Bedrock Setting) |
| Figure 1.3-8 | Conceptual Model of DNAPL Fate and Transport in a Karst Aquifer |
| Figure 2.1-1 | Regional Geology |
| Figure 2.1-2 | Flow Measurement Locations of Codorus Creek and Tributaries |
| Figure 2.1-3 | 9/2/2014 Seepage Run Survey Stream Flow Measurements |
| Figure 2.1-4 | Location of Repaired Wells |
| Figure 2.2-1 | Drilling Program, Supplemental Remedial Investigation Part 2 |
| Figure 2.2-2 | West Building 2 and Building 58 Source Area Investigations |
| Figure 2.2-3 | MW-137A(434.5-435') Chemistry Graph – Ethene Compounds |
| Figure 2.2-4 | MW-136A(434-434.5') Chemistry Graph – Ethene Compounds |
| Figure 2.2-5 | ERI Line Location and High-Resolution, Geo-Referenced Orthophotograph |
| Figure 2.2-6 | Well Locations South of Site |
| Figure 2.2-7 | Borehole Geophysics Locations Showing Strike and Dip Measurements |
| Figure 2.2-8 | Groundwater Velocity Test Results – MW-137A (283-298 feet bgs) |
| Figure 2.2-9 | Groundwater Elevation Contour Map (November 22, 2013) |

August 2016/Revised March 2018

| | |
|---------------|--|
| Figure 2.3-1 | Timeline of Phase 3 Testing and Monitoring |
| Figure 2.3-2 | Water Level Recorder and Weather Station Locations – 2013 - Present |
| Figure 2.3-3 | Northeast Property Boundary Area Monitoring Locations |
| Figure 2.3-4 | NPBA Groundwater Elevation Contour Map (August 8, 2013) Non-Pumping Conditions |
| Figure 2.3-5 | Cross Section E-E' Fully Recovered Piezometric Levels in the NPBA |
| Figure 2.3-6 | Building 3 Lift Station Shutdown Monitoring Locations |
| Figure 2.3-7 | Multiparameter Recorder Locations |
| Figure 2.3-8 | Selection of Codorus Creek Surface Water Sampling Locations |
| Figure 2.3-9 | Sulphorhodamine B in CW-20 Injection Point |
| Figure 2.3-10 | Dye Injection and Monitoring Locations |
| Figure 2.3-11 | USGS Gage Location |
| Figure 2.3-12 | Groundwater Elevation Contour Map (May 5, 2014) Pumping Conditions |
| Figure 2.3-13 | Groundwater Elevation Contour Map (October 7, 2014) Non-Pumping Conditions |
| Figure 2.3-14 | 2014 Comprehensive Sampling Program Locations |
| Figure 2.3-15 | 2013 and 2014 MNA Sample Locations |
| Figure 2.3-16 | Groundwater Elevation Contour Map (January 16, 2014) Non-Pumping Conditions |
| Figure 2.3-17 | 2015 Comprehensive Sampling Program Locations |
| Figure 2.3-18 | Groundwater Elevation Contour Map, September 3, 2015 |
| Figure 3.1-1 | Cross Section A-A' – Stratigraphy and Equipotential Contours |
| Figure 3.1-2 | Cross Section B-B' – Stratigraphy and Equipotential Contours |
| Figure 3.1-3 | Cross Section C-C' – Stratigraphy and Equipotential Contours |
| Figure 3.1-4 | Cross Section D-D' – Stratigraphy and Equipotential Contours |
| Figure 3.1-5 | Cross Section A-A' – TCE Plume |

| | |
|---------------|--|
| Figure 3.1-6 | Cross Section A-A' – PCE Plume |
| Figure 3.1-7 | Cross Section A-A' – cis12DCE Plume |
| Figure 3.1-8 | Cross Section D-D' – TCE Plume |
| Figure 3.1-9 | Cross Section D-D' – PCE Plume |
| Figure 3.1-10 | Cross Section D-D' – cis12DCE Plume |
| Figure 3.1-11 | MW-138A Chemistry Graph – Ethene Compounds |
| Figure 3.1-12 | Cross Section B-B' – TCE Plume |
| Figure 3.1-13 | Cross Section B-B' – PCE Plume |
| Figure 3.1-14 | Cross Section B-B' – cis12DCE Plume |
| Figure 3.1-15 | Cross Section C-C' – TCE Plume |
| Figure 3.1-16 | Cross Section C-C' – PCE Plume |
| Figure 3.1-17 | Cross Section C-C' – cis12DCE Plume |
| Figure 3.1-18 | Northeastern Property Boundary Area Monitored Shutdown (Chemistry Data Post-Shutdown) |
| Figure 3.1-19 | Northeastern Property Boundary Area Monitored Shutdown (Chemistry Data – 2014 Comprehensive Event) |
| Figure 3.1-20 | Southern Property Boundary Area Vapor Intrusion Investigation Study Area Location Map |
| Figure 3.1-21 | Southern Property Boundary Area Vapor Intrusion Investigation Well Locations |
| Figure 3.1-22 | Southern Property Boundary Area Vapor Intrusion Investigation Water Table Contour Map |
| Figure 3.1-23 | Southern Property Boundary Area Vapor Intrusion Investigation Cross Sections F-F' and G-G' |
| Figure 3.1-24 | Southern Property Boundary Area Shallow Groundwater Investigation Chemistry Results |
| Figure 3.1-25 | South Plume Area (SPA) Geology, Groundwater Elevation and TCE Plume |
| Figure 3.1-26 | South Plume Area (SPA) PCE Plume |

- Figure 3.1-27 Detections of D&C Red #28, October 2014
- Figure 3.1-28 SW-8 Dye Tracer Analysis – Fluorescein
- Figure 3.1-29 Rhodamine WT in MW-147A Injected 12/17/13 (Non-pumping conditions)
- Figure 3.1-30 Cross Section C-C' Rhodamine WT Injection in MW-147A on 12/17/13 (Non-pumping conditions)
- Figure 3.1-31 Fluorescein in MW-99D Injected 12/17/13 (Non-pumping conditions)
- Figure 3.1-32 Cross Section C-C' Fluorescein Injection in MW-99D on 12/17/13 (Non-pumping conditions)
- Figure 3.1-33 Photograph of Fluorescein Dye Seepage into Codorus Creek
- Figure 3.1-34 Eosine in MW-100D Injected 12/17/13 (Non-pumping conditions)
- Figure 3.1-35 Cross Section C-C' Eosine Injection in MW-100D on 12/17/13 (Non-pumping conditions)
- Figure 3.1-36 Cross Section C-C' Dye Injection Tracking
- Figure 3.1-37 TCE Plume and Piezometric Contours 310' Above Mean Sea Level (October 7, 2014 Non-pumping conditions)
- Figure 3.1-38 TCE Plume and Piezometric Contours 210' Above Mean Sea Level (October 7, 2014 Non-pumping conditions)
- Figure 3.1-39 TCE Plume and Piezometric Contours 110' Above Mean Sea Level (October 7, 2014 Non-pumping conditions)
- Figure 3.1-40 PCE Plume and Piezometric Contours 310' Above Mean Sea Level (October 7, 2014 Non-pumping conditions)
- Figure 3.1-41 PCE Plume and Piezometric Contours 210' Above Mean Sea Level (October 7, 2014 Non-pumping conditions)
- Figure 3.1-42 PCE Plume and Piezometric Contours 110' Above Mean Sea Level (October 7, 2014 Non-pumping conditions)
- Figure 3.1-43 cis12DCE Plume and Piezometric Contours 310' Above Mean Sea Level (October 7, 2014 Non-pumping conditions)
- Figure 3.1-44 cis12DCE Plume and Piezometric Contours 210' Above Mean Sea Level (October 7, 2014 Non-pumping conditions)
- Figure 3.1-45 cis12DCE Plume and Piezometric Contours 110' Above Mean Sea Level (October 7, 2014 Non-pumping conditions)

August 2016/Revised March 2018

| | |
|--------------|--|
| Figure 3.2-1 | Water Level Response to Precipitation in Well MW-145A – October 2013 |
| Figure 3.2-2 | MW-136A Area Potentiometric Elevations |
| Figure 3.2-3 | Green 8 in CW-20 Injected 1/31/14 |
| Figure 3.2-4 | SW-17 Green 8 Detections |
| Figure 3.2-5 | Sulphorhodamine B in CW-17 Injected 9/12/14 |
| Figure 3.2-6 | SW-13 Sulphorhodamine B Detections – 2 nd Test at CW-17 |
| Figure 3.2-7 | MW-98S Sulphorhodamine B Detections – 2 nd Test at CW-17 |
| Figure 3.2-8 | MW-74S Sulphorhodamine B Detections – 2 nd Test at CW-17 |
| Figure 3.3-1 | MW-136A Detailed Profile |
| Figure 3.3-2 | MW-136A (270-348') Chemistry – Ethenes |
| Figure 3.3-3 | MW-136A (356-356.5') Chemistry – Ethenes |
| Figure 3.3-4 | MW-136A (372.5-373') Chemistry – Ethenes |
| Figure 3.3-5 | MW-136A (434-434.5') Chemistry – Ethenes |
| Figure 3.3-6 | MW-136A (459.5-460') Chemistry – Ethenes |
| Figure 3.3-7 | MW-136A PCE Series with % Parent Compounds |
| Figure 3.3-8 | MW-136A and Other Wells - Potentiometric Elevations |
| Figure 3.5-1 | Building 3 Footer Drain System Annual Monitoring Locations |
| Figure 3.5-2 | SW-WPL Area MW-136A Vertical Extent Shutdown Graph |
| Figure 3.5-3 | Building 2 Area MW-137A Vertical Extent Shutdown Graph |
| Figure 3.5-4 | Building 4 Area MW-140A Vertical Extent Shutdown Graph |
| Figure 3.5-5 | Central Plant Area MW-139A Vertical Extent Shutdown Graph |
| Figure 3.5-6 | SW-WPL Area CW-20 Vertical Extent Shutdown Graph |
| Figure 3.5-7 | Photo of Sulphorhodamine B from Remediation System Effluent |
| Figure 3.5-8 | Sulphorhodamine B in CW-20 Injected 11/11/13 (pumping conditions) |
| Figure 3.5-9 | SW-6 Chemistry Graphs |

| | |
|---------------|---|
| Figure 3.5-10 | SW-8 Chemistry Graphs |
| Figure 3.5-11 | SW-17 Chemistry Graphs |
| Figure 3.5-12 | Photo of Piping in SW-17 |
| Figure 3.5-13 | SW-15 Chemistry Graphs |
| Figure 3.5-14 | SW-26 Chemistry Graphs |
| Figure 3.5-15 | SW-26 Chemistry with CW-20 Pumping Rates |
| Figure 3.5-16 | MW-136A Potentiometric Elevations |
| Figure 3.5-17 | SW-29 Chemistry Graphs |
| Figure 3.5-18 | Codorus Creek Base Flow Separation (using USGS PART Program) |
| Figure 3.5-19 | SW-8 Concentration vs Time Compared to % Base Flow |
| Figure 3.5-20 | SW-13 Concentration vs Time Compared to % Base Flow |
| Figure 3.5-21 | SW-29 Concentration vs Time Compared to % Base Flow |
| Figure 3.5-22 | SW-17 Concentration vs Time Compared to % Base Flow and Alkalinity |
| Figure 3.5-23 | Surface Water Concentrations Under Non-Pumping Conditions |
| Figure 3.5-24 | Surface Water Concentrations Under Pumping Conditions |
| Figure 3.6-1 | Eosine Capture (Pumping Conditions) |
| Figure 3.6-2 | WPL and Bldg 2 Transducers (Graph) for June 1, 2015 Rain Event |
| Figure 3.6-3 | Groundwater Elevation Contour Map (June 3, 2015) Pumping Conditions |
| Figure 3.6-4 | SW-17 Chemistry and MW-37D Hydrograph |
| Figure 4.0-1 | Traces of Conceptual Site Model Cross Sections |
| Figure 4.0-2 | Conceptual Site Model Cross Section A-A' Non-pumping Conditions |
| Figure 4.0-3 | Conceptual Site Model Cross Section A-A' Pumping Conditions |
| Figure 4.0-4 | Conceptual Site Model Cross Section B-B' South of Site |
| Figure 4.1-1 | Photograph of Pinnacled Bedrock Surface |
| Figure 4.1-2 | Epikarst Surface (Top of Bedrock) |

Plates (Volume 3 of 4)

| | |
|---------|---|
| Plate 1 | Site Wide TCE Plume Shallow Groundwater Chemistry |
| Plate 2 | Site Wide PCE Plume Shallow Groundwater Chemistry |
| Plate 3 | Site Wide cis12DCE Shallow Groundwater Chemistry |